



MISE EN PLACE DU KIT DE REPARATION INSTALLATION OF THE KIT OF REPAIR EINFÜHRUNG DES REPARATURSATZ




KRUPS

ADDENDUM



RINCAGE LONG - LANGES SPÖLEN
LONG RINSING - LANGE SPOELBEURT
RISCIACQUO LUNGO - ACLARADO LARGO
LAVAGEM DEMORADA - LANG SKYLLING
HOSSZU ÖBLITES - LANG SKYLLING
DLHE PREPLACHOVANIE
LANG SKÖLJNING
DLOUHE OPLÁCHNUTÍ



DEMONTAGE / DISMANTLING / AUSBAU



REMONTAGE / REASSEMBLY / WIEDERZUSAMMENBAUEN



XP7200..

08/11/06

ESPRESSERIA

1/14

KRUPS

1



2





3



4



5



XP7200..


08/11/06

ESPRESSERIA


2/14

KRUPS


6




7




8






9



10



11



XP7200..

08/11/06

ESPRESSERIA

3/14

KRUPS

12




Ancien moulin à café
Old coffee mill
Alt Kaffemühle

13




Nouveau moulin à café
New coffee mill
Neue Kaffemühle


14






15



16



17










XP7200..

08/11/06

ESPRESSERIA

4/14

KRUPS



XP7200..

08/11/06

ESPRESSERIA

5/14


KRUPS

24


Nouvelle pompe + joint
 New pump + O ring
 Neue Pumpe + Runddichtring




25




26






27



28



29



XP7200..


08/11/06

ESPRESSERIA


6/14

KRUPS


30




31




32






33



34



35











XP7200..

08/11/06

ESPRESSERIA

7/14

KRUPS



XP7200..


08/11/06

ESPRESSERIA


8/14

KRUPS


42




43



44





45



46



47



XP7200..

08/11/06

ESPRESSERIA

9/14

KRUPS

48




49



50





51



52



53



XP7200..

08/11/06

ESPRESSERIA

10/14

KRUPS

54




55






56



57



58



XP7200..




08/11/06

ESPRESSERIA

11/14

KRUPS

CONTROLES ET TESTS APRES REMONTAGE CHECKS AND TESTS AFTER REASSEMBLY KONTROLLEN UND TESTEN NACHDEM WIEDERZUSAMMENBAUEN




XP7200..



08/11/06

ESPRESSERIA

12/14



CONSEIL D'EMBALLAGE
THE COUNCIL OF PACKING
VERPACKUNGSRAT








XP7200..

08/11/06

ESPRESSERIA

13/14

KRUPS



XP7200..

08/11/06

ESPRESSERIA

14/14